



SKODA Octavia: 1GUL207			
Vinnnumber:	TMBJG7NEXE0204406	Versionname:	OCTAVIA COMBI GreenLine Ambition 110PK
First Registrationdate:	5/05/2014	Fiscalpower:	
Expertise Mileage:	105143	Power Kw:	81
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	No	Compressor	Yes
Total cost ex VAT			662,20
Roof, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Bump(s), PDR - Knock out without painting			142,20





Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display