



**RENAULT Trafic: 1AQY225**

Vinnumber:	<b>VF1FLBHA6BY379553</b>	Versionname:	<b>TRAFIC 29 B/F SWB L1H1 Confort 115pk</b>
First Registrationdate:	<b>7/03/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>153573</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV16</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	
Alarm	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/16/105 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Jack	<b>No</b>
-------------	-----------	------	-----------

Total cost ex VAT	396,32
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Jack, Missing, E - Replace	42,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s) and scratch(es), It - Spot repair	115,56



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	