



**RENAULT Megane: 1FHQ533**

Vinnumber:	<b>VF1KZ140648184236</b>	Versionname:	<b>MEGANE GT Energy TomTom Ed.110PK</b>
First Registrationdate:	<b>1/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>137339</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3123</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>Tow bar removable</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 T Steel</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 1304,68

Wheel cover F L, Damaged, E - Replace 30,00



Radio, Worn, Acceptable 0,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Seat cover F L, Hole, Smart repair 64,32



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Damaged, E - Replace 30,00



Wing R L, Bad repair, Paint 0,00



Backrest cover R L, Hole, Smart repair 64,32



Ceiling, Hole, Smart repair 64,32



Wheel cover R R, Damaged, E - Replace 30,00





Luggage space cover, Strained , Repair/replace (lump sum) 20,00



Seat cover F R, Stain, Cleaning 25,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover F R, Damaged, E - Replace 30,00



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Centre console, Hole, Smart repair 110,64

