


RENAULT Megane: 1GIP832

Vinnnumber:	VF1KZNA0650183683	Versionname:	MEGANE BRE Energy Bose Ed.130PK
First Registrationdate:	18/02/2014	Fiscalpower:	
Expertise Mileage:	117146	Power Kw:	96
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3401
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/89 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5,5 mm	Fr.R.	Michelin: 5,5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT **724,76**

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) **95,00**



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door frame R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), It - Spot repair 115,56



Wing R L, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 356,20



License plate F, Damaged, Repair/replace (lump sum) 0,00

