



**VOLKSWAGEN PASSAT: 1FHY827**

Vinnnumber:	<b>WVWZZZ3CZDE092649</b>	Versionname:	<b>VAR Comfortline BMT 105PK</b>
First Registrationdate:	<b>3/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>127050</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4115</b>
Maintenance:	<b>OVER 28000 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Sun Roof electric	
GPS storage	<b>HD</b>	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunction		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar removable</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>818,55</b>
-------------------	---------------

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------



Bonnet, Bump(s), Le - Replace and paint	<b>0,00</b>
-----------------------------------------	-------------



Wing F R, Bump(s), Acceptable 0,00



Roof pillar L, Hail damage, PDR - Knock out without painting 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Unclasp(ed), N - Mount/Dismount 96,00



Rocker panel inner R R, Scratch(es), Acceptable 0,00



Wing R L, Bump(s), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Rear spoiler, Hail damage, PDR - Hail 0,00



Roof pillar R, Hail damage, PDR - Knock out without painting 0,00



Roof, Hail damage, PDR - Hail	0,00
-------------------------------	------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	404,20
---------------------------------------------------------------------	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
----------------------------------------	------

