



## SEAT Alhambra: 1HSC088

Vinnnumber:	<b>VSSZZZ7NZFV504506</b>	Versionname:	<b>ALHAMBRA</b>
First Registrationdate:	<b>18/09/2014</b>	Ecom.Exec.Limit.DSG	<b>136PK Aut.</b>
Expertise Mileage:	<b>204127</b>	Fiscalpower:	
Bodytype:	<b>MPV</b>	Power Kw:	<b>100</b>
Gearbox:	<b>Automatic</b>	Body color	<b>Black</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Battery functioning	<b>Yes</b>	Oil level	<b>OK</b>
Number of doors	<b>5</b>	Parking lot	<b>4612</b>
Number of seats	<b>7</b>		
Number head rests	<b>6</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/50/17/98 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 3 mm</b>	Re.R.	<b>Kleber: 3 mm</b>

## Assistance equipment

Total cost ex VAT	710,64
Centre console, Damaged, E - Replace	78,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Crack, E - Replace	560,64
--------------------------------	--------



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Headrest R M, Missing, E - Replace	72,00



Wing F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sliding door R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	