




RENAULT Grand Scenic: 1DMQ364			
Vinnnumber:	VF1JZ14A647316200	Versionname:	GR.SCENIC Energ.Business 5pl.FAP 110PK
First Registrationdate:	25/06/2012	Fiscalpower:	
Expertise Mileage:	164762	Power Kw:	81
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options		
Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	Tow bar fixed
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT	831,83		
Wing R L, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>			
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35		





Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

