



VOLKSWAGEN Golf: 1HAU129			
Vinnnumber:	<b>WVWZZZAUZEP604634</b>	Versionname:	<b>GOLF VAR Highline 105PK</b>
First Registrationdate:	<b>5/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>135198</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Beige</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1322</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>


Total cost ex VAT	<b>211,80</b>
Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>

No pictures to display

Door R L, Bad repair, Acceptable	<b>0,00</b>
----------------------------------	-------------



Rear window, Scratch(es), E - Replace	<b>0,00</b>
---------------------------------------	-------------



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Bad repair, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bad repair, Acceptable 0,00



Door R R, Repaired, Acceptable 0,00

*No pictures to display*