



**RENAULT Grand Scenic: 1FGK443**

Vinnnumber:	<b>VF1JZ14M649140690</b>	Versionname:	<b>GRAND SCENIC Privil?ge</b>
First Registrationdate:	<b>21/06/2013</b>	Fiscalpower:	<b>5pl.110PK</b>
Expertise Mileage:	<b>161939</b>	Power Kw:	<b>81</b>
Bodytype:	<b>MPV</b>	Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2127</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather and alcantara</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/17/95 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 768,92

Door F R, Bump(s), PDR - Knock out without painting 63,00



Rearview mirror L complete, Broken, E - Replace 168,00



Bonnet, Scratch(es), Acceptable 0,00



Sill outer R, Bump(s), Acceptable 0,00



Outer door handle R R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), It - Spot repair 115,56



Alloy rim F L, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Door R L, Bump(s), Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

