


VOLKSWAGEN Golf: 1GHR925

Vinnnumber:	WVWZZZAUZEP551240	Versionname:	GOLF VAR Highline 105PK
First Registrationdate:	11/02/2014	Fiscalpower:	
Expertise Mileage:	104121	Power Kw:	77
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4819
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	Tow bar fixed
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	315,18
Tailgate, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Dirty, Cleaning	0,00
<i>No pictures to display</i>	
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18





Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display