



MERCEDES C180d: 1LSH656

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WDD2052361F276074 | Versionname: | |
| First Registrationdate: | 23/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 175390 | Power Kw: | 85 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | SERV B IN 6500KM | Parking lot: | 1120 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | SD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | Tow bar fixed |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 225/45/18/95 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Bridgestone: 8 mm | Re.R. | Bridgestone: 8 mm |

Assistance equipment

| | |
|---|--------|
| Total cost ex VAT | 210,56 |
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|---|--------|
| Front bumper, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rear window, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door frame R L, Scratch(es), It - Spot repair | 115,56 |

