



BMW 3: 1FJK057

Vinnnumber:	WBA3D91060F467454	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	16/07/2013	Fiscalpower:	
Expertise Mileage:	152427	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2613
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2429,53

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Wheel cover F R, Damaged, E - Replace 30,00






Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Wing R L, Chemical polution, LI - Repair and paint (complete) 308,20



Door R R, Chemical polution, LI - Repair and paint (complete) 318,35



Door panel F R, Damaged, E - Replace 114,00



Wheel cover R R, Damaged, E - Replace 30,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80






Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door panel R R, Damaged, E - Replace 114,00



Tailgate, Chemical polution, LI - Repair and paint (complete) 301,68



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display