



AUDI A3: 1HEX908

Vinnumber:	WAUZZZ8V7FA004175	Versionname:	A3 SB Attraction 136PK
First Registrationdate:	3/07/2014	Fiscalpower:	
Expertise Mileage:	25007	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1127
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	SD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 W LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	2472,55
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Front bumper, Scratch(es), LI - Repair and paint (complete)	235,80
---	---------------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 356,20



Covering interior front pillar L, Burned, Smart repair 110,64



Roof, Bump(s), PDR - Knock out without painting 82,80



Rearlight R tailgate, Hole, E - Replace 87,00



Ignition key, Missing, E - Replace 150,00

No pictures to display


Interior, Smell, Ozone treatment 152,58

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 259,80



Central pillar R, Bump(s), PDR - Knock out without painting 82,80



Wing F R, Scratch(es), Acceptable 0,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Ceiling, Burned, Smart repair 64,32



Bumper R, Damaged, E - Replace 62,00

