


**AUDI A5: 1GS117**

|                         |                          |              |                                     |
|-------------------------|--------------------------|--------------|-------------------------------------|
| Vinnnumber:             | <b>WAUZZZ8T7EA054331</b> | Versionname: | <b>A5 SB Multitr.DPF 150PK Aut.</b> |
| First Registrationdate: | <b>15/04/2014</b>        | Fiscalpower: |                                     |
| Expertise Mileage:      | <b>125815</b>            | Power Kw:    | <b>110</b>                          |
| Bodytype:               |                          | Body color   | <b>Black</b>                        |
| Gearbox:                | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                      |
| Transmission:           | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                    |
| Fueltype:               | <b>Diesel</b>            | Oil level    | <b>OK</b>                           |
| Battery functioning     | <b>Yes</b>               | Parking lot  | <b>3229</b>                         |
| Number of doors         | <b>5</b>                 |              |                                     |
| Number of seats         | <b>4</b>                 |              |                                     |
| Number head rests       | <b>4</b>                 |              |                                     |
| Rims summer             | <b>Aluminium</b>         |              |                                     |
| Category                | <b>Passenger Car</b>     |              |                                     |
| Oil level               | <b>OK</b>                |              |                                     |

**Options**

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| Radio CD                       |                              | Central consol F     |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |
| GPS storage                    |                              | Rear parking sensors |
| Windows electric F             |                              |                      |
| Windows electric R             |                              |                      |
| Cruise Control                 |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Seats F heated                 |                              |                      |
| Radio multimedia               |                              |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining leather</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/50/17/94 Y LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|               | Re.L.                            | <b>Michelin: 5 mm</b>    | Re.R. | <b>Michelin: 5 mm</b>    |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|





 Total cost ex VAT 2277,03

 Alloy rim R R, Scratch(es), Acceptable 0,00
*No pictures to display*

 Wing R R, Damaged, LI - Repair and paint (complete) 369,84

 Wing R L, Scratch(es), Acceptable 0,00
*No pictures to display*

 Door F L, Scratch(es), Acceptable 0,00
*No pictures to display*

|  |        |
|--|--------|
| Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)                  | 264,21 |
|    |        |
| Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)                  | 254,16 |
|    |        |
| Tailgate, Scratch(es), Acceptable  | 0,00   |
| <i>No pictures to display</i>  |        |
| Bonnet, Stone chip(s), Acceptable  | 0,00   |
| <i>No pictures to display</i>  |        |
| Door R R, Damaged, LI - Repair and paint (complete)                                  | 526,02 |
|     |        |
| Front bumper, Damaged, Le - Replace and paint  | 862,80 |
|  |        |