



BMW 116: 1FFD384

Vinnnumber:	WBA1C91070J512635	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	12/06/2013	Fiscalpower:	
Expertise Mileage:	123550	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2117
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1352,33
-------------------	----------------

Wing R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 283,80



Wing F L, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



MOT Certificate, Incomplete, P - Check 0,00



Bonnet, Scratch(es), 67 - Polish 55,19



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 366,35



Wing F R, Scratch(es), Acceptable 0,00



Maintenance, Maintenance, Execute 0,00



Wing R L, Bump(s), Acceptable 0,00



Backrest cover F L, Scratch(es), Acceptable 0,00



Door F L, Bump(s), Acceptable 0,00



Tailgate, Scratch(es), 67 - Polish

55,19

