


AUDI A5: 1GQV914

Vinnnumber:	WAUZZZ8T4EA069806	Versionname:	A5 SB TDie S-line DPF
First Registrationdate:	13/05/2014	Fiscalpower:	136PK
Expertise Mileage:	92763	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	-100KM OF 4 DAGEN	Parking lot:	1716
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Laser	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/18/93 Y LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	970,37
-------------------	---------------

Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Tyre R L, Damaged, Acceptable	0,00
-------------------------------	-------------

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Tailgate, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door F R, Repaired, Acceptable	0,00
--------------------------------	-------------



Wing F L, Scratch(es), LI - Repair and paint (complete) 288,21



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tyre F L, Damaged, Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Bumper R, Repaired, Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 302,16



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



MOT Certificate, Missing, Acceptable 0,00



Door R R, Repaired, Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



