



AUDI A3: 1HKR983			
Vinnnumber:	WAUZZZ8V0FA003577	Versionname:	A3 SB Ambition S-line 110PK
First Registrationdate:	12/08/2014	Fiscalpower:	
Expertise Mileage:	128922	Power Kw:	81
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1626
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		


Options	
Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	SD
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/40/18/92 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	943,92
Ceiling, Hole, Smart repair	64,32



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Floor covering F R, Stain, Cleaning 0,00

No pictures to display

Covering interior front pillar L, Hole, I - Repair 60,00



Protection plate M, Missing, E - Replace 74,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror basis L, Scratch(es), Acceptable 0,00

No pictures to display


Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 306,80



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), Windscreen repair 58,80





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Stain, Acceptable 0,00

No pictures to display