



CITROEN C4: 1FMH359

Vinnumber:	VF7NC9HP0DY559346	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	173698	Power Kw:	68
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3302
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2553,44
-------------------	----------------








Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

Door L R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
	
Interior, Dirty, Cleaning	50,00
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
	
Rearview mirror housing R, Scratch(es), Smart repair	110,64
	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
	
Bumper grille F R, Missing, E - Replace	32,40
	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display