


BMW 3: KG9021

Vinnnumber:	WBA3K11070F834417	Versionname:	3 TOURING 318d 143PK
First Registrationdate:	16/07/2014	Fiscalpower:	
Expertise Mileage:	145446	Power Kw:	105
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3526
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			618,70
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Windscreen, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Sill outer R, Scratch(es), LI - Repair and paint (complete)			310,50



Front bumper, Bad repair, Acceptable	0,00
--------------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

