


BMW X3: XX6703

Vinnnumber:	WBAWZ510700523595	Versionname:	2.0 XDRIVE20D (140KW)
First Registrationdate:	14/12/2016	Fiscalpower:	4WD
Expertise Mileage:	42812	Power Kw:	140
Bodytype:	SUV	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3812
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			818,02
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Trunk lid covering R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Luggage space cover, Missing, E - Replace			288,00



Tailgate, Bump(s), LI - Repair and paint (complete)	530,02
---	--------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display