



## AUDI A3: 1DPO250

|                         |                          |              |                             |
|-------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber:              | <b>WAUZZZ8P3DA014717</b> | Versionname: | <b>A3 SB Attraction</b>     |
| First Registrationdate: | <b>16/07/2012</b>        | Fiscalpower: | <b>Start/Stop DPF 105PK</b> |
| Expertise Mileage:      | <b>109037</b>            | Power Kw:    | <b>77</b>                   |
| Bodytype:               | <b>Hatchback</b>         | Body color:  | <b>Black</b>                |
| Gearbox:                | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>            |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>3122</b>                 |
| Number of doors:        | <b>5</b>                 |              |                             |
| Number of seats:        | <b>5</b>                 |              |                             |
| Number head rests:      | <b>5</b>                 |              |                             |
| Rims summer:            | <b>Aluminium</b>         |              |                             |
| Category:               | <b>Passenger Car</b>     |              |                             |
| Oil level:              | <b>OK</b>                |              |                             |

## Options

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 | Type of Tow bar              |
| Steering wheel multifunctional | <b>Tow bar removable</b>     |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                  |                      |       |                      |
|---------------|----------------------------------|----------------------|-------|----------------------|
|               | <b>205/55/16/91 V LightMetal</b> |                      |       |                      |
| Summer tyres: | Fr.L.                            | <b>Pirelli: 4 mm</b> | Fr.R. | <b>Pirelli: 4 mm</b> |
|               | Re.L.                            | <b>Pirelli: 5 mm</b> | Re.R. | <b>Pirelli: 5 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |        |
|---|--------|
| Total cost ex VAT   | 290,08 |
| Door F L, Scratch(es), Acceptable                           | 0,00   |
| <i>No pictures to display</i>                               |        |
| Bumper R, Scratch(es), Acceptable                           | 0,00   |
| <i>No pictures to display</i>                               |        |
| Door R R, Scratch(es), Acceptable                           | 0,00   |
| <i>No pictures to display</i>                               |        |
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |



|  |      |
|--|------|
| Roof pillar R, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

*No pictures to display*

|   |             |
|---|-------------|
| <b>Windscreen, Scratch(es), E - Replace</b> | <b>0,00</b> |
|---|-------------|



|  |             |
|--|-------------|
| <b>Wing R R, Scratch(es), Acceptable</b> | <b>0,00</b> |
|--|-------------|

*No pictures to display*

|  |             |
|--|-------------|
| <b>Door F R, Scratch(es), Acceptable</b> | <b>0,00</b> |
|--|-------------|

*No pictures to display*

|  |             |
|--|-------------|
| <b>Door R L, Scratch(es), Acceptable</b> | <b>0,00</b> |
|--|-------------|

*No pictures to display*