




BMW 3: 1GPE109			
Vinnumber:	<b>WBA3D11000J626810</b>	Versionname:	<b>3 BER 318d 136PK</b>
First Registrationdate:	<b>24/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>97980</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2811</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

Options	
Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 7 mm</b>	Fr.R.	<b>Goodyear: 7 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

Assistance equipment	
Total cost ex VAT	1083,70
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Damaged, E - Replace	235,20
-------------------------------------	--------



Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

