



BMW 5: 1FHY779

Vinnumber:	WBAMX11010C979024	Versionname:	5 TOURING 520d
First Registrationdate:	3/07/2013	Fiscalpower:	Start/Stop 163PK
Expertise Mileage:	92761	Power Kw:	120
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1312
Maintenance:	OVER 29000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	HD	Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Total cost ex VAT	417,72
Interior, Damaged, Acceptable	0,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Sill trim L, Bump(s), It - Spot repair 115,56



Bodywork, Damaged, Acceptable 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 302,16

