



BMW 5 TOURING: 1LHR003			
Vinnnumber:	WBA5L51060G090056	Versionname:	2.0 520D (140KW) XDRIVE AUTO TOURING
First Registrationdate:	1/10/2015	Fiscalpower:	
Expertise Mileage:	144087	Power Kw:	140
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1228
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting LED
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		923,45	
Alloy rim R R, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)		254,16	



Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), LI - Repair and paint (complete)	348,09



Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Instrument panel cover, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

