



**CITROEN Berlingo: PW9014**

Vinnnumber:	<b>VF77B9HF0CN516534</b>	Versionname:	<b>BERLINGO B/F Kort Pro 90PK</b>
First Registrationdate:	<b>25/05/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>209623</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3409</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	469,91
-------------------	--------

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display