


FORD S Max: 1FPT188

Vinnnumber:	WF0SXXGBWSDG58966	Versionname:	S-MAX Titanium St/St DPF
First Registrationdate:	18/09/2013	Fiscalpower:	115PK
Expertise Mileage:	185556	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3726
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	508,04
-------------------	--------

Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------



Floor covering F L, Hole, Smart repair	64,32
--	-------



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Scratch(es), It - Spot repair 115,56



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Protection plate M, Tear, E - Replace 74,00



Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display