



MERCEDES B: 1GFM188

Vinnnumber:	WDD2462121J233056	Versionname:	B 180CDI BE Edition 109PK
First Registrationdate:	24/01/2014	Fiscalpower:	
Expertise Mileage:	37191	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2722
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 8 mm	Re.R.	Dunlop: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT		145,56	
Bumper F R, Scratch(es), It - Spot repair		115,56	



Wheel cover R L, Scratch(es), Acceptable	0,00
---	-------------

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display