


CITROEN C4 Picasso: 1DKC396

| | | | |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | VF7UA9HR8CJ601095 | Versionname: | GR.C4 PICAS. e-HDi |
| First Registrationdate: | 7/06/2012 | Fiscalpower: | Bus.GPS FAP BMP 112PK |
| Expertise Mileage: | 77282 | Power Kw: | 82 |
| Bodytype: | MPV | Body color: | Blue |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2832 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/55/16/93 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | |
|---|--------|
| Total cost ex VAT | 318,35 |
| Door R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rocker panel inner F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Maintenance book, Missing, E - Replace | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover F L, Worn, Acceptable | 0,00 |



| | |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |

| | |
|---|--------|
| Door F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Bump(s), LI - Repair and paint (complete) | 318,35 |

