



**CITROEN C4 Picasso: 1HGf656**

Vinnnumber:	<b>VF73AAHXMEJ705029</b>	Versionname:	<b>GR.C4 PICASSO BlueHi Exclusive 150PK</b>
First Registrationdate:	<b>14/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>153386</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3325</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

TV/DVD screen R		Panoramic roof
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/17/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>1127,51</b>
<b>Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>



**Front bumper, Scratch(es), LI - Repair and paint (complete)**

**211,80**



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Engine protective plate, Tear, E - Replace 62,00



Door R L, Bump(s), LI - Repair and paint (complete) 318,35



Alloy rim R L polished, Rust, Acceptable 0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror glass L, Crack, E - Replace 18,00



Sill outer R, Bump(s) and scratch(es), It - Spot repair 115,56

