



**FORD S Max: 1HCS820**

|                                    |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber:                        | <b>WF0SXXGBWSET45205</b> | Versionname: | <b>S-MAX Trend Style St/St</b> |
| First Registrationdate:            | <b>19/06/2014</b>        | Fiscalpower: | <b>DPF 115PK</b>               |
| Expertise Mileage:                 | <b>55754</b>             | Power Kw:    | <b>85</b>                      |
| Bodytype:                          | <b>MPV</b>               | Body color:  | <b>Brown</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1208</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>7</b>                 |              |                                |
| Number head rests:                 | <b>7</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

**Options**

|  |  |
|--|--|
| Radio CD   | Central consol F                         |
| Windows electric F                                   | Luggage cover                            |
| Windows electric R                                   | Rear parking sensors                     |
| Cruise Control                                       | Type of Tow bar <b>Tow bar removable</b> |
| Steering wheel multifunctional                       |  |
| Type of headlighting <b>Headlighting Halogen</b>     |  |
| Type of GPS <b>GPS big screen color</b>              |  |
| Type of Lining <b>Lining fabrics</b>                 |  |
| Type of climate control <b>Autom climate control</b> |  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/50/17/98 W LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 6 mm</b> | Fr.R. | <b>Michelin: 6 mm</b> |
|               | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                       |        |
|---------------------------------------|--------|
| Total cost ex VAT                     | 206,00 |
| Protection plate M, Tear, E - Replace | 74,00  |



Door trim R R, Strained , E - Replace 132,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

|   |      |
|---|------|
| Front bumper, Difference in color, Acceptable | 0,00 |
|---|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display