



**FORD Mondeo: 1GDV398**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>WFOEXXGBBEDG05316</b> | Versionname: | <b>MONDEO BER ECONetic Titanium Style 115PK</b> |
| First Registrationdate:            | <b>10/01/2014</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>179242</b>            | Power Kw:    | <b>85</b>                                       |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Brown</b>                                    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                  |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2313</b>                                     |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |                          |
|--------------------------------|------------------------------|--------------------------|
| Radio CD                       | Central consol F             |                          |
| Windows electric F             | Luggage cover                |                          |
| Windows electric R             | Front parking sensors        |                          |
| Cruise Control                 | Rear parking sensors         |                          |
| Steering wheel multifunctional | Type of Tow bar              | <b>Tow bar removable</b> |
| Seats F heated                 |                              |                          |
| Radio multimedia               |                              |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                          |
| Type of Lining                 | <b>Lining leather</b>        |                          |
| Type of climate control        | <b>Autom climate control</b> |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>215/60/16/99 V LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Semperit: 7 mm</b> | Fr.R. | <b>Semperit: 7 mm</b> |
|                                  | Re.L. | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|                       |            |
|-----------------------|------------|
| Emergency spare wheel | <b>Yes</b> |
|-----------------------|------------|

|  |        |
|--|--------|
| Total cost ex VAT  | 518,60 |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00  |



|                                      |      |
|--------------------------------------|------|
| Sill outer R, Bad repair, Acceptable | 0,00 |
|--------------------------------------|------|



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

