


OPEL Astra: 1HAN271

Vinnnumber:	WOLPD6E67EG070076	Versionname:	ASTRA BER ecoFLEX Enjoy St/St 110PK
First Registrationdate:	4/06/2014	Fiscalpower:	
Expertise Mileage:	55108	Power Kw:	81
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3332
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1280,24
Roof pillar L, Bump(s), Acceptable	0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 316,18



Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display