



AUDI A6: 1JHV059			
Vinnumber:	<b>WAUZZZ4G3FN048190</b>	Versionname:	<b>A6 AVANT Ultra 5-tr. 190PK Aut.</b>
First Registrationdate:	<b>24/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>198631</b>	Power Kw:	<b>140</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2414</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>








Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>245/45/18/100 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Vredestein: 6 mm</b>	Fr.R.	<b>Vredestein: 6 mm</b>
	Re.L.	<b>Vredestein: 7 mm</b>	Re.R.	<b>Vredestein: 7 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>190,00</b>
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R L, Stone chip(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Windscreen, Damaged, E - Replace			<b>0,00</b>



Alloy rim R R, Scratch(es), I I - Repair and paint (complete)			<b>95,00</b>
---	--	--	--------------

			
			<b>Alloy rim R L, Scratch(es), LI - Repair and paint (complete)</b> <span style="float: right;">95,00</span>
			<b>Door F R, Scratch(es), Acceptable</b> <span style="float: right;">0,00</span> <i>No pictures to display</i>