


MERCEDES C: 1FEM496

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber: | WDD2042021G133784 | Versionname: | C BRE 220CDI BE Edition Avantgarde 163PK |
| First Registrationdate: | 7/06/2013 | Fiscalpower: | |
| Expertise Mileage: | 67696 | Power Kw: | 120 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 1328 |
| Maintenance: | B1 + 310 Dagen | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | HD |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|---|---------------|
| Total cost ex VAT | 115,56 |
| Door F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F R, Scratch(es), It - Spot repair | 115,56 |



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display