


MERCEDES CLA 200: 1GNI517

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WDD1173011N079214 | Versionname: | CDI |
| First Registrationdate: | 18/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 107561 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | A1 IN 178 JOURS | Parking lot: | 3306 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| GPS storage | |
| GPS storage | HD |
| Windows electric F | |
| Windows electric R | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 6 mm | Fr.R. | Continental: 6 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 534,56 |
|-------------------|--------|

| | |
|--|-------|
| Windscreen, Stone chip(s), Windscreen repair | 88,20 |
|--|-------|



| | |
|---|------|
| Door F R, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|


No pictures to display

| | |
|-------------------------------|------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

| | |
|--|--------|
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Sill trim R, Scratch(es), It - Spot repair | 115,56 |



| | |
|---|--------|
| Bumper R, Bump(s), LI - Repair and paint (complete) | 235,80 |
|---|--------|



| | |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

| | |
|-----------------------------------|------|
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), Acceptable | 0,00 |

| | |
|--|-------|
| <i>No pictures to display</i> | |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |

