



RENAULT Grand Scenic: 1FCM892

Vinnnumber:	VF1JZ14M649067153	Versionname:	GRAND SCENIC Business Spl.110PK
First Registrationdate:	24/05/2013	Fiscalpower:	
Expertise Mileage:	113225	Power Kw:	81
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2331
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 3016,47

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door moulding Lower R R, Scratch(es), It - Spot repair 115,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Central pillar R, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Rocker panel inner R L, Damaged, LI - Repair and paint (complete) 115,56



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Bump(s), LI - Repair and paint (complete) 318,35



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror glass L, Damaged, E - Replace 18,00

