



RENAULT CLIO: 1PAG391			
Vinnnumber:	VF15R0J0A55436042	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	20/05/2016	Fiscalpower:	
Expertise Mileage:	78286	Power Kw:	66
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2111
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	756,82
Bonnet, Bump(s), LI - Repair and paint (complete)	232,06



Wheel cover R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
--	---------------

(complete)



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Damaged, E - Replace 24,00

