


**RENAULT CLIO: 1KUF409**

Vinnnumber:	<b>VF15RJL0H53062259</b>	Versionname:	<b>1.5 ENERGY DCI 90E EXPRESSION</b>
First Registrationdate:	<b>6/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>121176</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Light Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2209</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunction			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/92 V Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>974,64</b>
Wheel cover R L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	<b>0,00</b>




Front bumper, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	<b>254,68</b>





Tailgate, Scratch(es), LI - Repair and paint (complete)

241,34



Bonnet, Scratch(es), LI - Repair and paint (complete)

232,06



Wing R R, Scratch(es), LI - Repair and paint (complete)

246,56

*No pictures to display*

Wheel cover R R, Scratch(es), Acceptable

0,00

*No pictures to display*