


RENAULT GRAND SCENIC: 1KVR898

Vinnnumber:	VF1JZ898BH53494649	Versionname:	1.5 ENERGY DCI 110 BOSE EDITION 7P
First Registrationdate:	15/07/2015	Fiscalpower:	
Expertise Mileage:	23121	Power Kw:	81
Bodytype:	MPV	Body color:	Burgundy
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2605
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1640,38
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



SD card, Missing, E - Replace	275,00
<i>No pictures to display</i>	
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	434,08




Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
--	--------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------

