



RENAULT Clio: 1EYG783			
Vinnnumber:	VF17R040H48670366	Versionname:	CLIO IV BRE Expression
First Registrationdate:	19/04/2013	Fiscalpower:	75PK
Expertise Mileage:	153731	Power Kw:	55
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1104
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Semperit: 8 mm	Re.R.	Semperit: 8 mm


Assistance equipment	
Total cost ex VAT	1111,82
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Damaged, E - Replace	24,00



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Wheel cover F L, Damaged, E - Replace 24,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Bumper R, Damaged, E - Replace 346,56



Wheel cover R R, Damaged, E - Replace 24,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 176,14



Wheel cover R L, Damaged, E - Replace

24,00

