


**RENAULT KADJAR: 1TJM169**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                         | <b>VF1RFE00859237095</b> | Versionname: |                  |
| First Registrationdate:            | <b>17/11/2017</b>        | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>30789</b>             | Power Kw:    | <b>81</b>        |
| Bodytype:                          |                          | Body color:  | <b>Black</b>     |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Maintenance:                       | <b>UITVOEREN</b>         | Parking lot: | <b>2204</b>      |
| Maintenance:                       | <b>NOT OK</b>            |              |                  |
| Battery functioning:               | <b>Yes</b>               |              |                  |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>5</b>                 |              |                  |
| Number head rests:                 | <b>5</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                  |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| GPS storage                    |                              | Central consol F      |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |
| Windows electric F             |                              | Front parking sensors |
| Windows electric R             |                              | Rear parking sensors  |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Alarm                          |                              |                       |
| Type of headlighting           | <b>Headlighting LED</b>      |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining semi-leather</b>   |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/45/19/96 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|               | Re.L.                            | <b>Continental: 7 mm</b> | Re.R. | <b>Continental: 7 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 468,35 |
|-------------------|--------|

|   |        |
|---|--------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|



|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Maintenance, Maintenance, Execute | 0,00 |
|-----------------------------------|------|

