



VOLKSWAGEN PASSAT: 1LNA543

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnnumber: | WVWZZZ3CZGE071889 | Versionname: | 1.6 TDI HIGHLINE |
| First Registrationdate: | 26/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 139739 | Power Kw: | 88 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3424 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather and alcantara |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 215/55/17/94 V LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 4 mm | Fr.R. | Pirelli: 4 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | |
|---|------|
| Total cost ex VAT | 0,00 |
| Alloy rim F R polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R R polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Increased paint layer, No repair | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |