


RENAULT Grand Scenic: 1GRR606

Vinnnumber:	VF1JZNAB650482604	Versionname:	Energy Intens 7pl.130PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	81597	Power Kw:	96
Bodytype:	MPV	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2720
Maintenance	GEEN INDICATIE		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	Tow bar fixed
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	955,05
-------------------	--------

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing R L, Scratch(es), Acceptable 0,00



Wing F L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Ceiling, Stain, Acceptable 0,00

