



VOLVO V60: 1EQL683

Vinnnumber:	YV1FW84A1D1129588	Versionname:	V60 D2 Kinetic St/St
First Registrationdate:	22/02/2013	Fiscalpower:	115PK
Expertise Mileage:	183095	Power Kw:	84
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1118
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1307,68
-------------------	----------------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Door F R, Bump(s), PDR - Knock out without painting 63,00

No pictures to display

Daytime running lights L, Crack, E - Replace 87,00



Headlight L, Crack, E - Replace 396,00



Front bumper, Damaged, LI - Repair and paint (complete) 259,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display