



<b>SKODA Octavia: 1GWN559</b>			
Vinnumber:	<b>TMBJG7NE5E0214826</b>	Versionname:	<b>OCTAVIA COMBI</b>
First Registrationdate:	<b>20/05/2014</b>	Fiscalpower:	<b>GreenLine Ambition 110PK</b>
Expertise Mileage:	<b>98819</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3331</b>
Maintenance:	<b>IN 4 DAGEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>195/65/15/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>No</b>
Total cost ex VAT			<b>2299,94</b>
Wing R L, Bump(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Maintenance, Maintenance, Execute			<b>0,00</b>



Engine, Maintenance, Execute	<b>0,00</b>
------------------------------	-------------



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Hole, E - Replace 360,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 316,18



Bumper R, Broken, Le - Replace and paint 651,00



Sill outer R, Bump(s) and scratch(es), It - Spot repair 259,56



Tyre repair kit, Missing, E - Replace 200,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Floor covering F L, Hole, E - Replace 252,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Door panel F L, Scratch(es), Smart repair	110,64
---	--------



Storage compartment housing, Incomplete, E - Replace	35,00
--	-------

