



VOLVO S80: 1FAP952

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | YV1AS84A1D1173277 | Versionname: | S80 BER D2 Kinetic S/S |
| First Registrationdate: | 8/05/2013 | Fiscalpower: | 115PK |
| Expertise Mileage: | 156355 | Power Kw: | 84 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | GEEN INDICATIE | Parking lot: | 2721 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | Rear parking sensors |
| GPS storage | HD |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/96 V LightMetal | | | |
| Summer tyres: | Fr.L. | Uniroyal: 7 mm | Fr.R. | Uniroyal: 7 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 252,56 |
|-------------------|---------------|

| | |
|-----------------------------------------------------|--------------|
| Door F L, Bump(s), PDR - Knock out without painting | 63,00 |
|-----------------------------------------------------|--------------|



| | |
|---------------------------------------------|---------------|
| Front bumper, Scratch(es), It - Spot repair | 115,56 |
|---------------------------------------------|---------------|



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------------|------|
| Bonnet, Chemical polution, Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------------|-------|
| Protection plate M, Tear, E - Replace | 74,00 |
|---------------------------------------|-------|



| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display