


**AUDI A6: 1EZQ806**

Vinnumber:	<b>WAUZZZ4G7DN136186</b>	Versionname:	<b>A6 AVANT Multitr.163PK</b>
First Registrationdate:	<b>30/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>189232</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Anthracite</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3728</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Seats electric F L	
Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Front parking sensors	
Steering wheel multifunction	Rear parking sensors	
Seats F heated	Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/60/16/98 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 3 mm</b>	Fr.R.	<b>Pirelli: 3 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

 Compressor **Yes**

Total cost ex VAT	1357,94
Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Door F R, Bump(s), LI - Repair and paint (complete) 382,02



Sill outer R, Scratch(es), LI - Repair and paint (complete) 372,60



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display