



AUDI A6: 1HHL024			
Vinnumber:	WAUZZZ4G3EN178937	Versionname:	A6 AVANT 136PK
First Registrationdate:	24/07/2014	Fiscalpower:	
Expertise Mileage:	162126	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4205
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control
Sport seats	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm


Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	1164,65
Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16



Floor covering F L, Hole, Smart repair	64,32
--	--------------




Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21




Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting 82,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Ignition key, Missing, E - Replace 150,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

