


AUDI A6: 1EQR252

Vinnumber:	WAUZZZ4G6DN106404	Versionname:	A6 AVANT 136PK
First Registrationdate:	25/02/2013	Fiscalpower:	
Expertise Mileage:	128315	Power Kw:	100
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3733
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/98 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Goodyear: 2,6 mm	Re.R.	Goodyear: 2,6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	430,02
-------------------	--------

Interior, Dirty, Acceptable	0,00
-----------------------------	------

No pictures to display

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Bump(s), LI - Repair and paint (complete)	430,02
---	--------

