



BMW 1: EB6192

Vinnnumber:	WBA1C91090P875130	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	8/12/2015	Fiscalpower:	
Expertise Mileage:	94229	Power Kw:	86
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3605
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1480,00
-------------------	----------------

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	---------------




Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Chemical cleaning 150,00





Door R L, Scratch(es), Acceptable

0,00

No pictures to display